



one-eighth inch = one foot
one-quarter inch = one foot
three-eighths inch = one foot
one-half inch = one foot
three-quarters inch = one foot
one inch = one foot
one and one-half inch = one foot
three inches = one foot



MECHANICAL ROOM SECTION
1/4"=1'-0"



0 2' 4' 8'
SCALE:1/4"=1'

Revisions		Date		 SCHENDT CONSULTING ENGINEERS CORPORATION * PH: (719) 637-8850 * * FAX (719) 632-0300 * 2912 BEACON ST. COLORADO SPRINGS, CO 80907		 GONZALES CONSULTING & ENGINEERING		P.O. Box 17868 GOLDEN, COLORADO 80402 PH: 303.386.3324 FX: 720.920.9004 RICARDO@GCECOLORADO.COM		Drawing Title MECHANICAL SECTIONS		Project Title REPLACEMENT OF ABSORPTION CHILLER		Project Number VA259-12-C-0219		Office of Facilities Management	
										Approved: Medical Center Director =		Location 2121 NORTH AVENUE GRAND JUNCTION, CO 81505		Building Number BLDG 9		Department of Veterans Affairs	
										Approved: Assistant Administrator, Engineering Department		Date 03/13/2013		Checked TBS		Drawn DJS	
														Drawing Number H4		Dwg. 3 of 16	